

**Flood Control Project Maintenance  
Levee Inspections**  
**LMA District Cover Sheet**  
**Spring 2009 Levee Inspection Results**

**Reclamation District No. 0150**

---

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\*

SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2009 Levee Inspection Results**

**Reclamation District No. 0150**

Waterway		Bank	Unit Miles
Unit No. 01 Sutter Slough		Left	0.54

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/8/2009 - 4/8/2009			
DWR Inspector	David Pesavento			
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

## Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Slough	Left	0.54	04/08/2009 04/08/2009	David Pesavento

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.01	0.53	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.332557 ° -121.583369 °	38.328162 ° -121.576373 °	Y	1
2	0.01	0.53	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.332556 ° -121.583337 °	38.328162 ° -121.576373 °	Y	2

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Slough	Left	0.54	04/08/2009 04/08/2009	David Pesavento

Levee Mile Report Line	1
Start Levee Mile	0.01
End Levee Mile	0.53
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Mow annual grass and weeds prior to fall inspection along the landward slope and 10' beyond.	



Levee Mile Report Line	2
Start Levee Mile	0.01
End Levee Mile	0.53
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Mow annual grass and weeds prior to fall inspection along the top 20' of the waterward slope.	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing  
U : Unacceptable      N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2009 Levee Inspection Results**

**Reclamation District No. 0150**

Waterway		Bank	Unit Miles
Unit No. 02 Sacramento River		Right	7.95

  

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/8/2009 - 4/8/2009			
DWR Inspector	David Pesavento			
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

## Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Right	7.95	04/08/2009 04/08/2009	David Pesavento

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.06	0.06	Earthen Levee	Erosion / Bank Caving	LS	M	Schedule repair of erosion site prior to the next inspection.	38.328907 ° -121.575574 °	38.328907 ° -121.575574 °	Y	95
2	0.16	0.16	Earthen Levee	Encroachments	WS	PO	Buildings	38.330047 ° -121.574538 °	38.330047 ° -121.574538 °	Y	49
3	0.24	0.24	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.330956 ° -121.573660 °	38.330956 ° -121.573660 °	Y	50
4	0.25	0.25	Earthen Levee	Encroachments	LS	CO	Landscaping	38.331035 ° -121.573502 °	38.331035 ° -121.573502 °	Y	4
5	0.27	0.27	Earthen Levee	Encroachments	LS	M	Tree or limb	38.331410 ° -121.573331 °	38.331410 ° -121.573331 °	Y	94
6	0.54	7.75	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.328199 ° -121.575933 °	38.411649 ° -121.521081 °		950
7	0.54	7.93	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.328197 ° -121.575935 °	38.413878 ° -121.522801 °		949
8	0.59	0.59	Earthen Levee	Trim / Thin Trees	WS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.334776 ° -121.569760 °	38.334776 ° -121.569760 °	Y	51
9	0.59	0.59	Earthen Levee	Trim / Thin Trees	WS	C	Trim trees to at least five feet above ground level.	38.334795 ° -121.569642 °	38.334795 ° -121.569642 °		5
10	0.98	1.00	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.339042 ° -121.565209 °	38.339307 ° -121.564860 °		6
11	1.09	1.12	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.340042 ° -121.563693 °	38.340397 ° -121.563375 °		7
12	1.25	1.28	Boat Survey	Boat Survey Erosion	LS	M	Inspector Comments: none	38.342078 ° -121.561436 °	38.341617 ° -121.561686 °		946
13	1.28	1.28	Earthen Levee	Encroachments	LS	PO	Landscaping	38.342229 ° -121.561694 °	38.342229 ° -121.561694 °		92
14	1.34	1.37	Earthen Levee	Encroachments	LS	PO	Landscaping	38.342969 ° -121.561196 °	38.343252 ° -121.560794 °		91
15	1.43	1.43	Boat Survey	Boat Survey Erosion	LS	U	Inspector Comments: slumping, caves	38.343536 ° -121.559636 °	38.343536 ° -121.559636 °		947
16	1.73	1.73	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.345574 ° -121.554909 °	38.345574 ° -121.554909 °		90
17	1.76	1.76	Earthen Levee	Encroachments	LS	PO	Landscaping	38.345675 ° -121.554407 °	38.345675 ° -121.554407 °		89

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway					Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 02 Sacramento River					Right	7.95	04/08/2009 04/08/2009	David Pesavento	

  

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
18	2.20	2.25	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.347104 ° -121.546744 °	° °		11
19	2.34	2.34	Earthen Levee	Encroachments	LS	PO	Landscaping	38.347361 ° -121.544280 °	38.347361 ° -121.544280 °		88
20	2.35	2.35	Earthen Levee	Encroachments	LS	M	Debris	38.347169 ° -121.544008 °	38.347169 ° -121.544008 °		87
21	2.50	2.50	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.347685 ° -121.541380 °	38.347685 ° -121.541380 °		13
22	2.79	2.79	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.349941 ° -121.537000 °	38.349941 ° -121.537000 °		86
23	2.80	2.80	Earthen Levee	Slope Stability	WS	M	Repair the levee slope damaged by foot traffic and prevent access where possible.	38.349965 ° -121.536820 °	38.349965 ° -121.536820 °		53
24	2.84	2.84	Earthen Levee	Encroachments	LS	M	Tree or limb	38.350375 ° -121.536152 °	38.350375 ° -121.536152 °	Y	15
25	3.02	3.06	Earthen Levee	Encroachments	LS	CO	Landscaping	38.352372 ° -121.534127 °	38.352802 ° -121.533638 °	Y	85
26	3.15	3.15	Earthen Levee	Trim / Thin Trees	LS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.353817 ° -121.532673 °	38.353817 ° -121.532673 °	Y	951
27	3.25	3.25	Earthen Levee	Vegetation	LS	M	Elderberries are blocking visibility and flood fight capability.	38.354876 ° -121.531531 °	38.354876 ° -121.531531 °		84
28	3.31	3.31	Earthen Levee	Trim / Thin Trees	LS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.355632 ° -121.530740 °	38.355632 ° -121.530740 °		952
29	3.48	3.51	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.357320 ° -121.528647 °	38.357660 ° -121.528272 °		19
30	3.53	3.56	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.357869 ° -121.528011 °	38.358158 ° -121.527642 °	Y	83
31	3.60	3.73	Earthen Levee	Encroachments	LS	CO	Landscaping	38.358565 ° -121.527153 °	38.359729 ° -121.525345 °		82
32	3.75	3.75	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.359830 ° -121.525167 °	38.359830 ° -121.525167 °		81
33	3.90	3.93	Earthen Levee	Encroachments	LS	PO	Landscaping	38.361419 ° -121.523225 °	38.361752 ° -121.522974 °	Y	80
34	4.18	4.18	Earthen Levee	Encroachments	LS	PO	Landscaping	38.365286 ° -121.522276 °	38.365286 ° -121.522276 °		953

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Right	7.95	04/08/2009 04/08/2009	David Pesavento

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
35	4.33	4.35	Earthen Levee	Encroachments	LS	CO	Landscaping	38.367442 ° -121.522427 °	38.367740 ° -121.522495 °	Y	24
36	4.37	4.41	Earthen Levee	Encroachments	LS	CO	Landscaping	38.368036 ° -121.522611 °	38.368540 ° -121.522729 °		79
37	4.46	4.46	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.369218 ° -121.522954 °	38.369218 ° -121.522954 °	Y	954
38	4.51	4.51	Earthen Levee	Trim / Thin Trees	LS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.369948 ° -121.523098 °	38.369948 ° -121.523098 °		955
39	4.55	4.57	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.370531 ° -121.523223 °	38.370762 ° -121.523293 °	Y	78
40	4.57	4.64	Boat Survey	Boat Survey Erosion	LS	U	Inspector Comments: slumping, tree hazards, animal burrows	38.371910 ° -121.523174 °	38.370934 ° -121.522968 °		948
41	4.76	4.76	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.373485 ° -121.523963 °	38.373485 ° -121.523963 °	Y	28
42	4.77	4.81	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.373549 ° -121.524208 °	38.374121 ° -121.524458 °		77
43	4.83	4.86	Earthen Levee	Encroachments	LS	PO	Landscaping	38.374296 ° -121.524591 °	38.374675 ° -121.524788 °		76
44	4.94	4.94	Interior Drainage & Piping Systems	Metal Pipes	WS	M	Inspector Comments: Abandoned metal pipe end not fully welded shut. Need to ensure that no water can travel through pipe from river.	38.375805 ° -121.525263 °	38.375805 ° -121.525263 °		956
45	4.98	4.98	Earthen Levee	Trim / Thin Trees	LS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.376274 ° -121.525468 °	38.376274 ° -121.525468 °		957
46	5.15	5.18	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.378715 ° -121.525458 °	38.379241 ° -121.525240 °		30
47	5.19	5.23	Earthen Levee	Encroachments	LS	PO	Landscaping	38.379286 ° -121.525256 °	38.379861 ° -121.525020 °		75
48	5.47	5.51	Earthen Levee	Trim / Thin Trees	LS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.382658 ° -121.522450 °	38.382979 ° -121.521904 °		74
49	5.56	5.56	Earthen Levee	Trim / Thin Trees	LS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.383402 ° -121.521150 °	38.383402 ° -121.521150 °		73
50	6.19	6.19	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: Century plant on landside slope	38.390582 ° -121.515101 °	38.390582 ° -121.515101 °		71

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Right	7.95	04/08/2009 04/08/2009	David Pesavento

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
51	6.28	6.28	Earthen Levee	Encroachments	LS	M	Debris Inspector Comments: Tires on landside slope	38.391838 ° -121.514887 °	38.391838 ° -121.514887 °	Y	70
52	6.38	6.38	Earthen Levee	Trim / Thin Trees	LS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.393263 ° -121.514710 °	38.393263 ° -121.514710 °		69
53	6.43	6.43	Earthen Levee	Encroachments	LS	PO	Landscaping	38.393867 ° -121.514615 °	38.393867 ° -121.514615 °		68
54	6.44	6.44	Earthen Levee	Trim / Thin Trees	LS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.394057 ° -121.514602 °	38.394057 ° -121.514602 °		67
55	6.45	6.48	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.394199 ° -121.514594 °	38.394615 ° -121.514586 °		66
56	6.49	6.51	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.394705 ° -121.514408 °	38.395083 ° -121.514458 °		38
57	6.54	6.57	Earthen Levee	Encroachments	LS	PO	Landscaping	38.395445 ° -121.514590 °	38.395931 ° -121.514604 °		65
58	6.54	6.54	Earthen Levee	Encroachments	WS	PO	Landscaping	38.395449 ° -121.514508 °	38.395456 ° -121.514509 °		958
59	6.68	6.72	Earthen Levee	Encroachments	LS	CO	Landscaping	38.397472 ° -121.514677 °	38.398065 ° -121.514738 °	Y	64
60	6.75	6.75	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.398540 ° -121.514697 °	38.398540 ° -121.514697 °	Y	40
61	6.76	6.79	Earthen Levee	Encroachments	LS	PO	Landscaping	38.398619 ° -121.514819 °	38.399044 ° -121.514855 °		63
62	6.80	6.80	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.399148 ° -121.514860 °	38.399148 ° -121.514860 °		62
63	6.84	6.84	Earthen Levee	Trim / Thin Trees	LS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.399689 ° -121.514926 °	38.399689 ° -121.514926 °		61
64	6.91	6.91	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.400761 ° -121.515047 °	38.400761 ° -121.515047 °		959
65	6.93	7.05	Earthen Levee	Encroachments	LS	PO	Landscaping	38.400936 ° -121.515173 °	38.402613 ° -121.515863 °	Y	60
66	7.07	7.12	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.402871 ° -121.515968 °	38.403521 ° -121.516250 °	Y	59
67	7.12	7.12	Earthen Levee	Trim / Thin Trees	LS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.403631 ° -121.516299 °	38.403631 ° -121.516299 °	Y	58

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Right	7.95	04/08/2009 04/08/2009	David Pesavento

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
68	7.18	7.18	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.404467 ° -121.516458 °	38.404467 ° -121.516458 °		45
69	7.25	7.25	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.405383 ° -121.516940 °	38.405383 ° -121.516940 °	Y	46
70	7.32	7.32	Earthen Levee	Encroachments	LS	M	Debris	38.406221 ° -121.517613 °	38.406221 ° -121.517613 °	Y	57
71	7.36	7.41	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.406817 ° -121.517687 °	38.407430 ° -121.518047 °	Y	48
72	7.92	7.92	Earthen Levee	Encroachments	LS	PO	Landscaping	38.413705 ° -121.522806 °	38.413705 ° -121.522806 °	Y	56

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Right	7.95	04/08/2009 04/08/2009	David Pesavento

Levee Mile Report Line	1
Start Levee Mile	0.06
End Levee Mile	0.06
Location	Land Side
Category	Earthen Levee
Item	Erosion / Bank Caving
Repair erosion/slumping on landside slope of levee at LM 0.06	



Levee Mile Report Line	2
Start Levee Mile	0.16
End Levee Mile	0.16
Location	Water Side
Category	Earthen Levee
Item	Encroachments
Building located on waterside of levee at LM 0.16	



Levee Mile Report Line	3
Start Levee Mile	0.24
End Levee Mile	0.24
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Remove century plant within 20' of waterside shoulder on waterside of the levee at LM 0.24	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Right	7.95	04/08/2009 04/08/2009	David Pesavento

Levee Mile Report Line	4
Start Levee Mile	0.25
End Levee Mile	0.25
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Landscaping on landward slope at LM 0.25 blocking view of levee slope.	



Levee Mile Report Line	5
Start Levee Mile	0.27
End Levee Mile	0.27
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Remove tree branches from landside of levee at LM 0.27	



Levee Mile Report Line	8
Start Levee Mile	0.59
End Levee Mile	0.59
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Trim trees above 5' from surface of the wateside of the levee within 20' from shoulder at LM 0.59	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

C : Corrected



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Right	7.95	04/08/2009 04/08/2009	David Pesavento

Levee Mile Report Line	24
Start Levee Mile	2.84
End Levee Mile	2.84
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Down tree limbs on landward slope at LM 2.84	



Levee Mile Report Line	25
Start Levee Mile	3.02
End Levee Mile	3.06
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Landscaping providing a screen for a residence on landside of levee from LM 3.02 to LM 3.06	



Levee Mile Report Line	26
Start Levee Mile	3.15
End Levee Mile	3.15
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Trim trees to 5' above surface of the levee to provide visibility of the landward levee slope at LM 3.15.	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Right	7.95	04/08/2009 04/08/2009	David Pesavento

Levee Mile Report Line	30
Start Levee Mile	3.53
End Levee Mile	3.56
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Remove/mow vegetation along landside of levee from LM 3.53 to LM 3.56	



Levee Mile Report Line	33
Start Levee Mile	3.90
End Levee Mile	3.93
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Landscaping in front of a residence on landside of levee from LM 3.90 to LM 3.93. The levee in this location is greater than 100' wide.	



Levee Mile Report Line	35
Start Levee Mile	4.33
End Levee Mile	4.35
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Landscaping (Oleander) on landward slope from 4.33 to 4.35	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Right	7.95	04/08/2009 04/08/2009	David Pesavento

Levee Mile Report Line	37
Start Levee Mile	4.46
End Levee Mile	4.46
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Remove brush to allow visibility of landward levee slope at LM 4.46.	



Levee Mile Report Line	39
Start Levee Mile	4.55
End Levee Mile	4.57
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Remove/mow vegetation on landside of levee to allow for visibility from LM 4.55 to LM 4.57	



Levee Mile Report Line	41
Start Levee Mile	4.76
End Levee Mile	4.76
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Century plant on waterward slope at LM 4.76	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Right	7.95	04/08/2009 04/08/2009	David Pesavento

Levee Mile Report Line	51
Start Levee Mile	6.28
End Levee Mile	6.28
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Remove tires from landside of levee at LM 6.28	



Levee Mile Report Line	59
Start Levee Mile	6.68
End Levee Mile	6.72
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Landscaping providing a screen for a residence on landside of levee from LM 6.68 to LM 6.72	



Levee Mile Report Line	60
Start Levee Mile	6.75
End Levee Mile	6.75
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Trim/thin trees and brush on waterside of levee within 20' of shoulder to allow visibility at LM 6.75	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

C : Corrected



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Right	7.95	04/08/2009 04/08/2009	David Pesavento

Levee Mile Report Line	65
Start Levee Mile	6.93
End Levee Mile	7.05
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Landscaping providing a screen for a residence on landside of levee from LM 6.93 to LM 7.05	



Levee Mile Report Line	66
Start Levee Mile	7.07
End Levee Mile	7.12
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Remove/mow vegetation along bottom of landside slope of levee from LM 7.07 to LM 7.12	



Levee Mile Report Line	67
Start Levee Mile	7.12
End Levee Mile	7.12
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Landscaping providing a screen for a residence on landside of levee at LM 7.12	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Right	7.95	04/08/2009 04/08/2009	David Pesavento

Levee Mile Report Line	69
Start Levee Mile	7.25
End Levee Mile	7.25
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Trim or remove brush to allow for visibility on landside of levee at LM 7.25	



Levee Mile Report Line	70
Start Levee Mile	7.32
End Levee Mile	7.32
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Remove pipes piled on landside of levee to at least 10' from levee toe at LM 7.32	



Levee Mile Report Line	71
Start Levee Mile	7.36
End Levee Mile	7.41
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Trim/thin trees and brush on landside of levee from LM 7.36 to LM 7.41	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Right	7.95	04/08/2009 04/08/2009	David Pesavento

Levee Mile Report Line	72
Start Levee Mile	7.92
End Levee Mile	7.92
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Landscaping on landside of levee at LM 7.92



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing  
U : Unacceptable      N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2009 Levee Inspection Results**

**Reclamation District No. 0150**

Waterway		Bank	Unit Miles
Unit No. 03 Elk Slough		Left	9.58

  

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/8/2009 - 4/8/2009			
DWR Inspector	David Pesavento			
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

## Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.58	04/08/2009 04/08/2009	David Pesavento

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.02	2.14	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.332941 ° -121.583567 °	38.354073 ° -121.568224 °		916
2	0.02	9.54	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.332943 ° -121.583581 °	38.413328 ° -121.523223 °		917
3	0.03	0.33	Earthen Levee	Vegetation	LS	U	Remove the wild growth other than native grasses from the levee slopes.	38.333111 ° -121.583532 °	38.337127 ° -121.581823 °	Y	918
4	0.09	0.09	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Regrade the crown roadway for proper drainage.	38.333924 ° -121.583471 °	38.333924 ° -121.583471 °	Y	919
5	0.21	0.21	Boat Survey	Boat Survey Erosion	CR	U	Inspector Comments: tree hazards, slumping	38.335655 ° -121.583258 °	38.335655 ° -121.583258 °		915
6	0.38	0.38	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: ice plant on land slope	38.337632 ° -121.581532 °	38.337632 ° -121.581532 °		42
7	0.43	0.43	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Regrade the crown roadway for proper drainage.	38.338404 ° -121.581392 °	38.338404 ° -121.581392 °		920
8	0.68	0.77	Earthen Levee	Crown Surface / Depressions / Rutting	CR	A	Add appropriate gravel or road base. Grade and compact.	38.341853 ° -121.580410 °	38.343123 ° -121.580351 °	Y	921
9	0.78	1.06	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Regrade the crown roadway for proper drainage. Inspector Comments: Rutting on surface of crown.	38.343322 ° -121.580462 °	38.347069 ° -121.578732 °		922
10	1.20	1.47	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Regrade the crown roadway for proper drainage. Inspector Comments: Rutting in surface of crown	38.347545 ° -121.576576 °	38.348356 ° -121.572431 °		923
11	1.22	1.22	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Regrade the crown roadway for proper drainage.	38.347613 ° -121.576182 °	38.347613 ° -121.576182 °	Y	9
12	1.23	1.23	Earthen Levee	Slope Stability	LS	M	Repair the levee slope damaged by vehicle traffic and prevent access where possible.	38.347607 ° -121.576130 °	38.347607 ° -121.576130 °	Y	10
13	1.66	1.66	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.351019 ° -121.572965 °	38.351019 ° -121.572965 °		43
14	2.03	2.06	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.354792 ° -121.569990 °	38.354689 ° -121.569417 °	Y	44
15	2.84	2.84	Earthen Levee	Encroachments	WS	M	Tree or limb Inspector Comments: Remove fallen tree from top 20' of waterside slope.	38.360210 ° -121.561546 °	38.360210 ° -121.561546 °	Y	924

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 03 Elk Slough						Left	9.58	04/08/2009 04/08/2009	David Pesavento	

  

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
16	2.88	2.88	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.360825 ° -121.561842 °	38.360825 ° -121.561842 °		925
17	3.01	9.54	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.362558 ° -121.562215 °	38.413346 ° -121.523269 °		926
18	3.43	3.48	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	38.363223 ° -121.555962 °	38.363953 ° -121.555382 °	Y	14
19	3.50	3.54	Earthen Levee	Encroachments	LS	PO	Landscaping	38.364251 ° -121.555321 °	38.364772 ° -121.555343 °	Y	47
20	3.75	3.75	Earthen Levee	Slope Stability	LS	M	Repair the levee slope damaged by vehicle traffic and prevent access where possible.	38.367305 ° -121.554984 °	38.367305 ° -121.554984 °	Y	927
21	3.77	3.77	Earthen Levee	Slope Stability	WS	M	Repair the levee slope damaged by foot traffic and prevent access where possible.	38.367393 ° -121.554528 °	38.367393 ° -121.554528 °	Y	15
22	3.95	3.95	Earthen Levee	Encroachments	LS	M	Debris	38.368118 ° -121.551509 °	38.368118 ° -121.551509 °	Y	48
23	4.38	4.38	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.373649 ° -121.550542 °	38.373649 ° -121.550542 °		50
24	4.46	4.46	Earthen Levee	Encroachments	LS	M	Prunings	38.374269 ° -121.549385 °	38.374269 ° -121.549385 °	Y	51
25	4.51	4.51	Earthen Levee	Encroachments	LS	M	Debris	38.374267 ° -121.548441 °	38.374267 ° -121.548441 °		52
26	4.55	4.58	Earthen Levee	Encroachments	LS	PO	Landscaping	38.374311 ° -121.547802 °	38.374368 ° -121.547263 °	Y	16
27	4.59	4.59	Earthen Levee	Trim / Thin Trees	WS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.374419 ° -121.547096 °	38.374419 ° -121.547096 °	Y	53
28	4.98	4.98	Earthen Levee	Encroachments	LS	M	Tree or limb	38.377601 ° -121.541549 °	38.377601 ° -121.541549 °		54
29	5.03	5.07	Earthen Levee	Encroachments	LS	PO	Landscaping	38.378203 ° -121.541048 °	38.378651 ° -121.540608 °		55
30	5.48	5.48	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.382109 ° -121.544321 °	38.382109 ° -121.544321 °		929
31	5.78	5.78	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.383990 ° -121.542977 °	38.383990 ° -121.542977 °		930
32	5.89	5.93	Earthen Levee	Encroachments	LS	PO	Fences	38.384363 ° -121.541161 °	38.384796 ° -121.540525 °		56

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 03 Elk Slough						Left	9.58	04/08/2009 04/08/2009	David Pesavento	

  

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
33	5.92	5.92	Earthen Levee	Encroachments	LS	M	Tree or limb	38.384648 ° -121.540669 °	38.384648 ° -121.540669 °		57
34	5.93	5.93	Earthen Levee	Encroachments	CR	CO	Buildings	38.384803 ° -121.540545 °	38.384803 ° -121.540545 °	Y	58
35	6.01	6.09	Earthen Levee	Encroachments	LS	PO	Landscaping	38.385752 ° -121.539905 °	38.386703 ° -121.540042 °		21
36	6.10	6.10	Earthen Levee	Encroachments	WS	M	Tree or limb Inspector Comments: Remove fallen tree from top 20' of waterside slope.	38.387027 ° -121.539968 °	38.387027 ° -121.539968 °	Y	931
37	6.11	6.12	Earthen Levee	Encroachments	LS	PO	Landscaping	38.386935 ° -121.540268 °	38.387096 ° -121.540500 °		23
38	6.24	6.31	Earthen Levee	Encroachments	LS	PO	Landscaping	38.388535 ° -121.541657 °	38.389391 ° -121.541901 °	Y	24
39	6.35	6.36	Earthen Levee	Encroachments	LS	PO	Landscaping	38.389700 ° -121.541462 °	38.389808 ° -121.541285 °		25
40	6.37	6.40	Earthen Levee	Encroachments	LS	PO	Landscaping	38.389858 ° -121.541155 °	38.390115 ° -121.540657 °	Y	26
41	6.44	6.44	Earthen Levee	Trim / Thin Trees	WS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.390492 ° -121.540111 °	38.390492 ° -121.540111 °		59
42	6.56	6.56	Earthen Levee	Encroachments	LS	PO	Landscaping	38.391616 ° -121.538378 °	38.391616 ° -121.538378 °		60
43	6.65	6.65	Earthen Levee	Encroachments	LS	M	Prunings	38.392858 ° -121.538085 °	38.392858 ° -121.538085 °	Y	28
44	6.71	6.71	Earthen Levee	Animal Control	LS	C	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.393624 ° -121.538390 °	38.393624 ° -121.538390 °		61
45	6.86	6.86	Earthen Levee	Encroachments	LS	PO	Equipment Inspector Comments: Trailer on ramp of landward slope	38.395633 ° -121.538018 °	38.395633 ° -121.538018 °	Y	932
46	6.86	6.86	Earthen Levee	Vegetation	LS	C	Remove the wild growth other than native grasses from the levee slopes.	38.395602 ° -121.537990 °	38.395602 ° -121.537990 °		62
47	6.87	6.95	Earthen Levee	Encroachments	LS	PO	Landscaping	38.395670 ° -121.537925 °	38.396027 ° -121.536575 °	Y	30
48	6.95	7.04	Earthen Levee	Encroachments	LS	PO	Landscaping	38.395015 ° -121.536319 °	38.396841 ° -121.535401 °		933
49	7.07	7.09	Earthen Levee	Encroachments	LS	PO	Landscaping	38.397180 ° -121.535140 °	38.397540 ° -121.535183 °		31

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 03 Elk Slough						Left	9.58	04/08/2009 04/08/2009	David Pesavento	

  

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
50	7.32	7.32	Earthen Levee	Encroachments	LS	M	Prunings	38.400643 ° -121.535991 °	38.400643 ° -121.535991 °		63
51	7.39	7.39	Earthen Levee	Encroachments	WS	PO	Landscaping	38.401481 ° -121.536876 °	38.401481 ° -121.536876 °		64
52	7.42	7.44	Earthen Levee	Encroachments	LS	PO	Landscaping	38.401738 ° -121.537127 °	38.401999 ° Y -121.537390 °		32
53	7.47	7.47	Earthen Levee	Encroachments	LS	PO	Landscaping	38.402319 ° -121.537744 °	38.402319 ° -121.537744 °		65
54	7.51	7.51	Earthen Levee	Encroachments	LS	M	Prunings	38.402735 ° -121.538140 °	38.402735 ° -121.538140 °		33
55	7.55	7.55	Earthen Levee	Encroachments	LS	PO	Landscaping	38.403161 ° -121.538610 °	38.403161 ° Y -121.538610 °		34
56	7.58	7.58	Earthen Levee	Encroachments	LS	PO	Landscaping	38.403621 ° -121.538822 °	38.403621 ° -121.538822 °		934
57	7.60	7.60	Earthen Levee	Encroachments	LS	M	Prunings	38.403795 ° -121.539205 °	38.403795 ° -121.539205 °		935
58	8.25	8.37	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.409113 ° -121.538367 °	38.408443 ° -121.536406 °		35
59	8.35	9.54	Earthen Levee	Vegetation	CR	M	Control annual grass and weeds on the levee slopes and easements.	° -121.523223 °	38.413324 ° Y -121.523223 °		936
60	8.46	8.46	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	38.407960 ° -121.534898 °	38.407960 ° Y -121.534898 °		66
61	8.48	8.48	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	38.407958 ° -121.534583 °	38.407958 ° -121.534583 °		67
62	8.52	8.62	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch Inspector Comments: Irrigation Ditch in landside toe	38.408238 ° -121.533866 °	38.409291 ° -121.532702 °		69
63	8.52	8.52	Earthen Levee	Animal Control	CR	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.408245 ° -121.533865 °	38.408245 ° -121.533865 °		68
64	8.59	8.59	Earthen Levee	Vegetation	LS	C	Remove the wild growth other than native grasses from the levee slopes.	38.408952 ° -121.533067 °	38.408952 ° -121.533067 °		70
65	9.16	9.16	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	38.415388 ° -121.528477 °	38.415388 ° -121.528477 °		71
66	9.31	9.38	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.413908 ° -121.526637 °	38.413243 ° -121.525808 °		39

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.58	04/08/2009 04/08/2009	David Pesavento

LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
67	9.35	9.35	Earthen Levee	Trim / Thin Trees	WS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.413433 ° -121.526180 °	38.413433 ° -121.526180 °		72
68	9.51	9.51	Earthen Levee	Trim / Thin Trees	WS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.413169 ° -121.523707 °	38.413169 ° -121.523707 °	Y	73
69	9.56	9.56	Earthen Levee	Trim / Thin Trees	WS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.413649 ° -121.523087 °	38.413649 ° -121.523087 °		74

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.58	04/08/2009 04/08/2009	David Pesavento

Levee Mile Report Line	3
Start Levee Mile	0.03
End Levee Mile	0.33
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Mow or remove tall (up to 5 feet) vegetation located on landward levee slope completely blocking visibility from LM 0.03 to LM 0.33.	



Levee Mile Report Line	4
Start Levee Mile	0.09
End Levee Mile	0.09
Location	Crown
Category	Earthen Levee
Item	Crown Surface / Depressions / Rutting
Re-grade crown access road to remove depressions at LM 0.09.	



Levee Mile Report Line	8
Start Levee Mile	0.68
End Levee Mile	0.77
Location	Crown
Category	Earthen Levee
Item	Crown Surface / Depressions / Rutting
Good gravel surface of crown access road from LM 0.68 to LM 0.77.	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.58	04/08/2009 04/08/2009	David Pesavento

Levee Mile Report Line	11
Start Levee Mile	1.22
End Levee Mile	1.22
Location	Crown
Category	Earthen Levee
Item	Crown Surface / Depressions / Rutting
Minor depression on levee crown at LM 1.22	



Levee Mile Report Line	12
Start Levee Mile	1.23
End Levee Mile	1.23
Location	Land Side
Category	Earthen Levee
Item	Slope Stability
Damage slope from foot traffic and rain runoff at LM 1.23	



Levee Mile Report Line	14
Start Levee Mile	2.03
End Levee Mile	2.06
Location	Land Side
Category	Earthen Levee
Item	Animal Control
Backfill or grout rodent holes at LM 2.03 to LM 2.06.	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

C : Corrected



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.58	04/08/2009 04/08/2009	David Pesavento

Levee Mile Report Line	15
Start Levee Mile	2.84
End Levee Mile	2.84
Location	Water Side
Category	Earthen Levee
Item	Encroachments
Remove fallen tree blocking visibility/access along top 20' of waterward slope at LM 2.84.	



Levee Mile Report Line	18
Start Levee Mile	3.43
End Levee Mile	3.48
Location	Water Side
Category	Earthen Levee
Item	Erosion / Bank Caving
Erosion damage on waterward toe from LM 3.43 to 3.48	



Levee Mile Report Line	19
Start Levee Mile	3.50
End Levee Mile	3.54
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Landscaping & garden on landward slope of levee at LM 3.50 to LM 3.54.	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.58	04/08/2009 04/08/2009	David Pesavento

Levee Mile Report Line	20
Start Levee Mile	3.75
End Levee Mile	3.75
Location	Land Side
Category	Earthen Levee
Item	Slope Stability
Repair minor damage to levee slope along landward ramp at LM 3.75.	



Levee Mile Report Line	21
Start Levee Mile	3.77
End Levee Mile	3.77
Location	Water Side
Category	Earthen Levee
Item	Slope Stability
Repair slope damaged by foot traffic at LM 3.77.	



Levee Mile Report Line	22
Start Levee Mile	3.95
End Levee Mile	3.95
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Debris pile on landward slope at LM 3.95.	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

C : Corrected



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.58	04/08/2009 04/08/2009	David Pesavento

Levee Mile Report Line	24
Start Levee Mile	4.46
End Levee Mile	4.46
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Remove pruning pile on landward slope at LM 4.46.	



Levee Mile Report Line	26
Start Levee Mile	4.55
End Levee Mile	4.58
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Landscaping blocking view of landward slope from 4.50 to 4.58	



Levee Mile Report Line	27
Start Levee Mile	4.59
End Levee Mile	4.59
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Thin/trim trees to allow for the top 20' waterward slope of levee to be seen at LM 4.59.	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.58	04/08/2009 04/08/2009	David Pesavento

Levee Mile Report Line	34
Start Levee Mile	5.93
End Levee Mile	5.93
Location	Crown
Category	Earthen Levee
Item	Encroachments

Building & associated landscaping on levee crown at LM 5.93.



Levee Mile Report Line	36
Start Levee Mile	6.10
End Levee Mile	6.10
Location	Water Side
Category	Earthen Levee
Item	Encroachments

Remove fallen tree branch from top 20' of waterward levee slope at LM 6.10.



Levee Mile Report Line	38
Start Levee Mile	6.24
End Levee Mile	6.31
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Oleander on landward slope blocking view of levee from LM 6.24 to 6.32



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

C : Corrected



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.58	04/08/2009 04/08/2009	David Pesavento

Levee Mile Report Line	40
Start Levee Mile	6.37
End Levee Mile	6.40
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Landscaping on landward slope blocking view from LM 6.37 to 6.40	



Levee Mile Report Line	43
Start Levee Mile	6.65
End Levee Mile	6.65
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Remove debris from landward slope at LM 6.65.	



Levee Mile Report Line	45
Start Levee Mile	6.86
End Levee Mile	6.86
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Remove Camper trailer parked along landard ramp at LM 6.86 and place a minimum of 10' from the toe of the levee.	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

C : Corrected



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.58	04/08/2009 04/08/2009	David Pesavento

Levee Mile Report Line	47
Start Levee Mile	6.87
End Levee Mile	6.95
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Landscaping on landward slope blocking view from LM 6.87 to 6.95	



Levee Mile Report Line	52
Start Levee Mile	7.42
End Levee Mile	7.44
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Landscaping on landward slope blocking view from LM 7.42 to 7.47	



Levee Mile Report Line	55
Start Levee Mile	7.55
End Levee Mile	7.55
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Landscaping on landward slope blocking view from LM 7.52 to 7.58	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**Reclamation District No. 0150**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.58	04/08/2009 04/08/2009	David Pesavento

Levee Mile Report Line	59
Start Levee Mile	8.35
End Levee Mile	9.54
Location	Crown
Category	Earthen Levee
Item	Vegetation
Remove all vegetation from the crown of the levee from LM 8.35 to 9.54 to provide visibility and to allow for vehicular access without risk of fire.	



Levee Mile Report Line	60
Start Levee Mile	8.46
End Levee Mile	8.46
Location	Water Side
Category	Earthen Levee
Item	Erosion / Bank Caving
Repair erosion on waterward slope near shoulder at LM 8.46.	



Levee Mile Report Line	68
Start Levee Mile	9.51
End Levee Mile	9.51
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Thin/trim trees to allow for visibility of top 20' of waterward slope at LM 9.51.	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

C : Corrected